

Job Loss Analysis

ID No: 2000070 Status: Closed Original Date: 13/Apr/2010

Last Review Date:

Organization:

SBU: GMfg

BU: Global Mfg Shared

Work Type: GMfg Manufacturing Shared (Process Engineering)

Title (Work Activity):

Process Engineering Relief Valve Sizing

Personal Protective Equipment (PPE)	Selected	Comments
Proper PPE per your Refinery Guidelines	Υ	

Site/Region:

Reviewers

Reviewers Name	Position	Date Approved
Michelle Johansen	Process Engineering Manger RI Refinery	13/Apr/10

Development Team

Development Team Member Name			
Malcolm White		Process Engineering Manager	
Joe Ninneman		Lead Process Engineer	
Gary Neville		Lead Process Engineer	
Andy Waterman		Lead Process Engineer	
Laura Edwards		Process Engineer	
Bryony Jones		Process Engineer	
Declan Carey		Process Engineer	
Elen Jones	X	Process Engineer	

Job Steps

No	Job Steps	Potential Hazard	Critical Actions
1.	Safety Relief Valve Data Sheet Availability.	Existing Data Sheet may no longer be valid, e.g. Plant may have been modified. Existing data sheet may be unavailable or the new safety relief valve being designed is for a brand new service.	Determine the size and type of relief valve installed and check against the data sheet. Generate a new Pressure Safety and/or Vacuum Relief Valve Data Sheet.

2.	Determining relief load.	Failure to identify potential scenarios for relief loads. Failure to capture the largest relief load, potential for relief valve to be undersized. Incorrect type of relief valve, e.g. balance bellows instead of conventional valve.	 For each pressure relief location, relief loads that result from one of the potential causes listed in FRS-DU-5057B Section 23.1 shall be listed. If a relief valve has multiple relief cases, the relief valve shall be sized per the case which results in the largest orifice area. Ensure back pressure calculation has been conducted. Review FRS-DU-5057B Section 18 – Selection of Pressure Relief Device.
3.	Review Relief Valve Location and Type Required.	 Relief valve incorrectly located. Incorrect type of relief valve in place. Incorrect type of relief valve, e.g. Balance bellows instead of conventional valve. The correct valve trim for liquid, vapour or 2 phase relief, to prevent damage to valve due to chattering or high blowdown of the valve. 	 Review FRS-DU-5057B Section 5 for Pressure Relief Valve Location Requirements. Review FRS-DU-5057B Section 6 and 12 for Temperature Relief Valve and Vacuum Relief Protection Requirements. Ensure back pressure calculation has been conducted. Review FRS-DU-5057B section 18 –Selection of Pressure Relief Device. Refer to FRS-DU-5057B Section 18.1 for liquid, vapour or 2 phase relief valve trim.
4	Sizing Pressure Relief Valve	Incorrect formulae used to determine the relief valve capacity. Incorrect relief valve nozzle effective area selected.	Review Section 5, FRS-DU-5056C – Pressure Relief Valve Capacity Formulae. Select the applicable formulae. Review Section 5.1, FRS-DU-5056C – Pressure Relief Valve Nozzle Effective Areas. Select applicable nozzle size. Check orifice size versus calculated size to confirm sufficient area for Swagelok type.

5	Reviewing the Flare Loads	1. Flare load incorrectly	1. Review FRS-DU-5057B
	Reviewing the Flare Loads	determined.	Section 24 - Flare Loads for
		Current flare system not	Flare System Sizing
		designed for additional load.	Review the determined flare
			load with Process Technology
			Department – Process
			Technology will examine the
			following:
			 The back pressure effect
			on the pressure relief
			valve capacity.
			 The impact on the flare
			header capacity –
			particularly for site wide
			conditions such as steam
			or power failure.
			The requirement for
			stress analysis in the case
			of high temperature relief.
			 Design features that may
			be necessary to limit or
			mitigate relief load.
			Pipe roughness has been
			used for hydraulic
			calculations.
			 Check pipe stresses for
			two phase flow.

6	Data Sheet Completion	Incomplete or incorrect data sheet preventing engineer from	Complete the relevant fields in the Site Standard Data Sheet.
		sheet preventing engineer from purchasing the correct valve.	
			using formulae from FRS-DU- 5057B&C
7	Data Sheet Verification	Incorrect calculations/ data sheet incorrectly completed ultimately resulting in the incorrect relief valve. Excessive inlet line pressure losses may result in relief valve chatter / damage or destruction. Excessive outlet line pressure losses may result in sonic flow / reduced relief valve capacity. Incorrect assessment of potential two phase flow will result in undersized relief devices / connecting piping. Flashing liquids (LPG) may result in cold embrittlement and subsequent failure of relief piping.	 Relief valve calculations to be checked by a Process Engineer, and approved by a Designated Process Engineer. Pressure drop data on inlet and outlet should be checked by a designated Process Engineer to assure correct assumptions. Determine if two phase flow is occurring and assure relief valve is designed correctly for this condition. If liquid is flashed across valve during relief, determine outlet line temperature to assure failure is not possible with design.

8	Cross Check Manufacturer's Valve with Original Data Sheet	Buyer purchased incorrect valve.	1a.Cross check Vendor's Data Sheet with the original Data Sheet. 1b. Confirm vendor's material of construction is suitable for the intended service. Refer to FRS-DU-5056-C, Section 8 – Materials for Pressure Relief Valves.
9	Documentation	1a. Operating Manuals/ Plant Files not updated. 1b. No record of the relief calculations/ data sheet. 2.Flare System Process Summary and Flare PFDs not updated.	 Relief calculations and data sheet to be documented as per FRS-DU-5057B&5056C Section 26 – Documentation. Typical documentation includes: Updating Operating Manual/Plant Files. Sketch of the unit and offsite flare system. Detailed calculations for all applicable scenarios not just the sizing case. Assure designated engineer and system such as MOC is in place to keep the Flare System Process data and Flare PFDs up to date.